
Service Bulletin: SB 91

DATE: July 17, 1996

GAME: Tales of the Arabian Nights

SUBJECT: Improper wire dressing on the vanishing magnet assembly.

On the vanishing magnet assembly, the cable tie that keeps the magnet coil wires in their proper place was improperly installed. Games made prior to July 16, 1996 might be affected and should be checked and corrected if wrong. The magnet is mounted to a plate (*Part #01-14179*).

One end of the plate has a 90 degree bend and 2 holes in that area. The cable tie should go from one hole and into the other hole. If dressed incorrectly, the wires may get cut by the plate. Please refer to the drawing below if necessary.

